



ONTAP升级后A250启动失败

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/A250_boot_failure_after_ONTAP_upgr...

Updated: Wed, 22 Apr 2026 07:28:41 GMT

适用场景

- A250
- ONTAP 9

问题描述

ONTAP升级后、A250的一个节点启动失败。它已显示以下信息、然后重新启动。

```
Version 2.20.1271. Copyright (C) 2023 American Megatrends, Inc.
```

```
BIOS Date: 08/25/2023 11:49:53 Ver: 17.10
```

```
BIOS boot from Primary SPI
```

```
Boot Loader version 8.1.1
```

```
Copyright (C) 2000-2003 Broadcom Corporation.
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Portions Copyright (C) 2002-2023 NetApp, Inc. All Rights Reserved.

ACPI RSDP Found at 0x68539000

Returning back to BIOS flash0a

Copyright(c) 2021 American Megatrends, Inc.