



CXone Mpower EXPERT

A700s ONTAP 从9.8P6升级到9.9.9.1P11失败

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/A700s_ONTAP_upgrade_from_9.8P6_...

Updated: Wed, 22 Apr 2026 04:07:56 GMT

适用场景

- AFF A700
- ONTAP 9.8P6
- ONTAP 9.9.91P11

问题描述

在将ONTAP 从9.8P6升级到9.9.91P11期间、一个节点暂停加载程序、其中：

```
NetApp Data ONTAP 9.8P6
...
Setting default boot image to
image1... done.
...
Loading NVRAM firmware version 1.3.8 (was 1.2.0.)
Programming NVRAM FW...
Programming meta for image 0
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
Image 0 valid.  
Resetting BB table  
Error: Failed to reset NAND BB table.  
Operation failed with code 5  
ERROR: BB table reset failed.  
REBOOTING TO LOAD NEW NVRAM FIRMWARE...  
WARNING: Aborting boot (sending SIGTERM to parent)!  
...  
LOADER-B>
```