



# CXone Mpower EXPERT

---

## 启用入站节点限制时发生控制器中断

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/controller\\_disruption\\_when\\_inbound\\_n...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/controller_disruption_when_inbound_n...)

Updated: Wed, 22 Apr 2026 07:31:27 GMT

### 适用场景

ONTAP 9

### 问题描述

节点崩溃、并显示以下崩溃字符串：

```
page fault (supervisor read data, page not present) on VA 0x343 cs:rip  
0x20:0xffffffff8c52c1f0 rflags 0x10202 in SK process repl_Handle_reg on release  
9.6P6 (C)
```

或

```
page fault (supervisor read data, page not present) on VA 0 cs:rip  
0x20:0xffffffff8a55a1cf rflags 0x10287 in SK processrepl_Handle_reg on release  
9.6P3 (C)
```