



设备无法在最大链路宽度降级时进行训练

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Device_failed_to_train_at_max_link_wi...

Updated: Wed, 22 Apr 2026 07:31:46 GMT

适用场景

AFF-A800

问题描述

- 安装卡后、节点无法启动
- 错误:
`PCI Bus initialization start.`
`Device B0/8/0 (SLOT-1) failed to train at max link width degraded`
`- Expected x16, actual x1`