



EMS会报告UnsestedMixOfIOM12和IOM6Shelves_Alert

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/EMS_reports_UnsupportedMixOfIOM1...

Updated: Wed, 22 Apr 2026 03:53:58 GMT

适用场景

ONTAP 9.3

问题描述

在同一堆栈中向IOM6磁盘架添加IOM12磁盘架时、EMS会报告警报。

示例：

```
[node04: pmcsas_asyncd_1: sas.config.badtransition:error]: Unsupported speed transition by expander WWN: 5:00a098:0077c81:3f at level 3 in SAS stack on adapter port 0c.
```

```
[node04: nchmd: hm.alert.raised:alert]: Alert Id =  
UnsupportedMixOfIOM12andIOM6Shelves_Alert , Alerting Resource =  
3353879937131547216:1 raised by monitor node-connect
```