



# CXone Mpower EXPERT

## ifgroup端口在ONTAP升级后发生闪烁

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/IFGroup\\_ports\\_flapping\\_after\\_ONTAP...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/IFGroup_ports_flapping_after_ONTAP...)

Updated: Wed, 22 Apr 2026 13:25:31 GMT

### 适用场景

- ONTAP 9
- LACP
- IFGroups

### 问题描述

- ONTAP升级后、ifgroup中的所有端口不会保持联机状态：
- 在EMS中可以多次看到以下内容：

[Node-01: vifmgr: vifmgr.portdown:notice]: A link down event was received on node Node-01, port e0a.

[Node-01: kernel: netif.linkUp:info]: Ethernet e0a: Link up.