



X1151A适配卡初始化失败

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Initialization_of_X1151A_X1148A_ada...

Updated: Wed, 22 Apr 2026 09:01:34 GMT

适用场景

- ONTAP 9
- AF-A400
- X1151A
- X1148A

问题描述

- EMS中存在错误

```
示例: Aug 09 14:33:59 [localhost:netif.init.failed:ALERT]: Initialization of network interface e5a failed due to unexpected software error mlx5_core err=0xffffffffb:110.
```

- 在ONTAP中看不到上述适配器卡上的端口

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information