



CXone Mpower EXPERT

IOM 升级需要冷交换

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/IOM_upgrade_requires_a_cold_swap

Updated: Wed, 22 Apr 2026 04:08:07 GMT

执行

执行

适用场景

SAS 磁盘架和基于 SAS 的机箱：

- DS4243
- DS4246
- DS2246

问题描述

- 本文介绍冷插拔升级所需的步骤。
- 如果要将磁盘架中的 IOM 模块更换为其他型号、则需要在更换期间关闭以下组件：
 - 连接到受影响磁盘架的所有节点。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

- 连接到受影响磁盘架的所有ATto网桥(如果适用)。
- 要更改IOM型号的磁盘架。
- 可能的升级：
 - IOM3到 IOM6
 - IOM3到 IOM12*
 - IOM6到 IOM12*

*请注意IOM3/IOM6 (Qsp)和IOM12 (MiniSAS-HD)之间的SAS端口差异