



CXone Mpower EXPERT

NIC端口已关闭

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/NIC_port_down

Updated: Wed, 22 Apr 2026 07:28:52 GMT

适用场景

ONTAP 9

问题描述

- NIC端口已关闭。
- `ifconfig -a TX` 受影响SFP的报告为 `-inf`。

```
e2b: flags=8843<UP,BROADCAST,RUNNING,SIMPLEX,MULTICAST> metric 0 mtu 1500
    uuid: f8146927-4cad-11ec-b538-d039ea3780f8
options=ec07bb<RXCSUM, TXCSUM, VLAN_MTU, VLAN_HWTAGGING, JUMBO_MTU, VLAN_HWCSUM, TSO4, TSO6, L
capabilities=ec07bb<RXCSUM, TXCSUM, VLAN_MTU, VLAN_HWTAGGING, JUMBO_MTU, VLAN_HWCSUM, TSO4, T
    ether 40:a6:b7:71:20:79
    media: Ethernet autoselect (autoselect <full-duplex>)
    status: no carrier
    supported media:
        media autoselect
        media 10GBase-SFI
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
media 1000Base-KX
media 10Gbase-LR
media 10Gbase-SR
media 10Gbase-Twinax
media 1000baseLX
media 1000baseSX
plugged: SFP/SFP+/SFP28 10G Base-SR (LC)
vendor: Intel Corp PN: FTLX8574D3BCV-IT SN: A4QAT70 DATE: 2020-12-19
module temperature: 21.67 C Voltage: 3.42 Volts
RX: 0.63 mW (-2.01 dBm) TX: 0.00 mW (-inf dBm)
```