



CXone Mpower EXPERT

节点不断重新加载、而不报告任何错误

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Node_fails_to_POST__during_ONTAP...

Updated: Wed, 22 Apr 2026 08:25:37 GMT

适用场景

- ONTAP 9
- FAS/AFF

问题描述

- 节点无法进行POST (加电自检)、并持续报告以下内容：

```
BIOS Version: 13.13
```

```
PEI start.
```

```
CPU PEI initialization.
```

```
Wait BMC self-test result.
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

BMC self-test: OK.

Running full memory initialization

BIOS Version: 13.13

PEI start.

CPU PEI initialization.

Wait BMC self-test result.

BMC self-test: OK.

Running full memory initialization.

- 从SP/BMC重新启动受影响的节点不会解析问题描述。