



CXone Mpower EXPERT

板载UTA2端口无响应

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Onboard_UTA2_ports_become_unres...

Updated: Wed, 22 Apr 2026 10:27:39 GMT

适用场景

- FAS2720
- ONTAP 9.7P5

问题描述

板载UTA2端口无响应、并显示以下错误：

示例：

```
[nodename: sched_monitor: sk.hog.runtime:notice]: Process e0c errq ran for 5024 milliseconds
```

```
[nodename: sched_monitor: mgr.stack.longrun.proc:notice]: Long running process: e0c errq
```