



## 重新启动时AFF A250出现"es.status.ModuleError"

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/ses\\_status\\_ModuleError\\_on\\_AFF\\_A25...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/ses_status_ModuleError_on_AFF_A25...)

Updated: Wed, 22 Apr 2026 08:36:02 GMT

### 适用场景

- AFF A250
- NS224NSM8E
- FAS500F

### 问题描述

AFF A250节点重新启动、配对节点在EMS中报告以下错误

```
[Node-01: dsa_worker2: ses.status.electronicsWarn:error]: NS224NSM8E (S/N  
XXXXXXXXXXXXXXXXXX) shelf 0 on channel 0s environmental monitoring warning for  
SES electronics 2: communication error. ; enclosure services hardware failed  
This element is on the rear of the shelf at the bottom, on shelf module (B).  
[Node-01: dsa_worker2: ses.status.ModuleError:alert]: NS224NSM8E (S/N  
XXXXXXXXXXXXXXXXXX) shelf 0 on channel 0s PCI switch error for PCI Switch 2:  
status not available; status not available. This element is on the rear of the  
shelf at the bottom, on shelf module (B).
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

