



CXone Mpower EXPERT

SSH在新控制器上不起作用

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/SSH_not_working_on_new_controllers

Updated: Wed, 22 Apr 2026 08:49:29 GMT

适用场景

- ONTAP 9
- FAS2720
- SSH

问题描述

- 对新节点进行初始配置后
- 通过SSH连接到新节点失败、并显示：

```
"Remote side unexpectedly closed network connection"
```

- 节点与启动SSH会话的客户端之间存在防火墙