



由于ONTAP版本混合、无法通过SNMP访问交换机

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Switch_not_reachable_via_SNMP_due...

Updated: Wed, 22 Apr 2026 13:25:31 GMT

适用场景

- 在同一集群中运行ONTAP 9.7及更早版本的ONTAP 9.8及更高版本
- 集群网络交换机

问题描述

- ONTAP升级后出现以下警报

```
SwitchCommunityString_Alert
```

```
Ethernet switch "clusterswitch1(12345678798)" with IP address "10.10.10.10" is not reachable via SNMP. Incorrect SNMP community string might be configured on the Ethernet switch.
```

- 在交换机上配置了正确的SNMP设置、ONTAP与交换机之间的网络和SNMP连接正常工作
- 已成功从ONTAP Ping和执行交换机管理IP并执行snmpwalk操作

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information