



CXone Mpower EXPERT

在集群交换机刷新期间发生意外的虚拟机管理程序接管

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Unexpected_CLAM_takeover_during_...

Updated: Wed, 22 Apr 2026 10:27:33 GMT

适用场景

- ONTAP 9
- NetApp CN1610 集群交换机
- Cisco N9K-C9336C-FX2 集群交换机

问题描述

在更换集群交换机期间、节点发生意外接管。在中 EMS

```
sk.panic: ALERT] Panic String: Received PANIC packet from partner, receiving message is (Coredump and takeover initiated because Connectivity, Liveliness and Availability Monitor (CLAM) has determined this node is out of quorum.) in SK process mcc_ic_kill_pkt_handler on release 9.10.1P15 (C)
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information