



CXone Mpower EXPERT

在 AF-A700s 系统中检测到不受支持的 HA 互连缆线

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Unsupported_HA_interconnect_cable_...

Updated: Wed, 22 Apr 2026 11:57:57 GMT

适用于

- AFF A700
- ONTAP 9.1P6 或更高版本

问题

已禁用接管，并且事件日志中可能会显示以下警报：

```
Mon Sep 14 01:00:00 +0000 [Node_name: statd: cf.takeover.disabled:alert]: HA mode, but takeover of partner is disabled.
```

```
Mon Sep 14 01:00:00 +0000 [Node_name: statd: ic.unsupportCable:error]: Detected unsupported Passive Copper 2m ID:00 cable with part number 112-00437.
```