



# CXone Mpower EXPERT

## 未正确显示不受支持的缆线

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Unsupported\\_cables\\_not\\_showing\\_cor...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Unsupported_cables_not_showing_cor...)

Updated: Wed, 22 Apr 2026 08:49:14 GMT

### 适用场景

- ONTAP 9
- FAS/AFA

### 问题描述

电缆未在Sysconfig输出中正确显示

```
Cluster::> system node run -node Cluster-01 -command "sysconfig -a" slot 0: 10 Gigabit Ethernet Controller IX5-  
SFP+ e0a MAC Address: 00:a0:98:b9:82:6d (auto-unknown-fd-up) SFP Vendor: Molex Inc. SFP Part Number:  
73929-0039 <-- Unsupported part number SFP Serial Number: XXXXXXXXXX e0b MAC Address:  
00:a0:98:b9:82:6e (auto-unknown-fd-up) SFP Vendor: Molex Inc. SFP Part Number: 73929-0039 <--  
Unsupported part number SFP Serial Number: XXXXXXXXXX
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information