



NiCE

H615C : DIMM初始化失败。(<DIMM-slot>)—已断言

https://kb-cn-stage.netapp.com/on-prem/SolidFire/hardware_Kbs/H615C__DIMM_initialization_fail_CP...

Updated: Thu, 04 Jun 2026 05:24:16 GMT

适用场景

NetApp H615 C

问题描述

- 在vSphere Client中、总内存显示为495.05 GB、而不是511.05 GB
- **BMC > System Inventory**(系统资源清册)，有一个大小为16384 MB的DIMM

注：正确的DIMM大小应为32768MB

- **BMC > IPMI Event Log > Event logs.** show `DIMM initialization fail. (CPU1_A0) - Asserted`

示例：

```
[Warning] [Extended DIMM POST Error] [OEM Record C1]
ManufacturerID:000315, Major Code:0A, Minor Code:03 (CPU1_A0)
```

```
[Warning] [POST Error] [System Firmware Progress] 0xA240 : DIMM
initialization fail. (CPU1_A0) - Asserted
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

[Warning] [Extended DIMM POST Error] [OEM Record C1]
ManufacturerID:000315, Major Code:30, Minor Code:2D (CPU1_A0)

[Warning] [POST Error] [System Firmware Progress] 0xA240 : DIMM
initialization fail. (CPU1_A0) - Asserted