



CXone Mpower EXPERT

由于 IP 重复，SVMDR 初始化失败

https://kb-cn-stage.netapp.com/on-prem/ontap/dp/SnapMirror/SnapMirror-KBs/SVMDR_intitilization_fa...

Updated: Wed, 22 Apr 2026 04:08:29 GMT

适用场景

- ONTAP 9
- SVMDR

问题描述

SVMDR 初始化失败，原因如下：

```
"Failed to apply the source Vserver configuration. Reason: Apply failed for  
Object: vifsbyname Method: baseline. Reason: Duplicate IP address<>."
```