



---

## ONTAP 升级后， AutoSupport 生成失败

[https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap\\_OS/OS-KBs/AutoSupport\\_generation\\_fails\\_after...](https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/AutoSupport_generation_fails_after...)

Updated: Wed, 22 Apr 2026 04:07:41 GMT

### 适用场景

ONTAP 已从 9.1 升级到 ONTAP 9.3 或更高版本

### 问题描述

- 未生成 AutoSupport
- `notifyd.log` 此文件将完全填充类似于以下内容的消息：

```
Mon Dec 14 2020 12:49:48 -08:00 [kern_notifyd:info:2405] fromXML: Could not get description for event "pvif_allLinksDown".
```