



CXone Mpower EXPERT

固件下载失败，操作超时

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/Firmware_Download_Failing_With_...

Updated: Wed, 22 Apr 2026 10:27:37 GMT

适用场景

ONTAP 9

问题描述

尝试下载存储磁盘固件失败、并显示以下错误消息。

错误消息：

```
::*> storage firmware download -node cluster1 -package-url http://downloads/  
software/firmware.zip
```

Error: command failed: Timeout:

```
Operation "storage_firmware_download_iterator::create_imp()" took longer than 25  
seconds to complete [from mgwd on node  
"cluster-01" (VSID: -1) to mgwd at 169.254.147.101]
```