



CXone Mpower EXPERT

节点在 NDU 期间变得无响应

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/node_become_unresponsive_durin...

Updated: Wed, 22 Apr 2026 08:35:01 GMT

适用于

- ONTAP 9
- AFF-A400
- 无中断升级 (NDU)

问题描述

- 在从 9.7P11 到 9.8P21 的 NDU 期间执行接管后，节点挂起，如下所示：

```
cluster1::*> Files /cfcard/x86_64/freebsd/image1/VERSION and /var/VERSION
differ
Terminated
.
Setting default boot image to image1...
done.
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
Uptime: 1489d3h52m22s
setting the MUX for SOL
[968 : 1040 CRIT
```

- BMC 日志未记录任何控制台错误或错误事件。