



CXone Mpower EXPERT

ONTAP API 失败：正在执行控制器更换操作

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/ONTAP_API_Failed_Controller_re...


Updated: Wed, 22 Apr 2026 07:28:53 GMT

适用于

- ONTAP 9.5
- ONTAP 升级验证
- 更换控制器

问题

在 ONTAP OS 更新验证期间，会弹出一个消息，报告以下错误：ONTAP API 失败：正在执行控制器更换操作



'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information