



CXone Mpower EXPERT

由于电池状态已删除，E 系列性能较慢

https://kb-cn-stage.netapp.com/on-prem/E-series/SANtricity-OS-Kbs/E-Series_Slow_performance_due...

Updated: Wed, 22 Apr 2026 11:21:19 GMT

适用场景

NetApp E 系列

问题描述

SANtricity 存储管理器或 SANtricity 系统管理器中出现以下警告：

- `REMOVED_BATTERY-Recovery Failure Type Code: 67`
- `WB_CACHING_FORCIBLY_DISABLED-Recovery Failure Type Code: 378`