



## 在E-Series上检测到主机多路径驱动程序配置错误

[https://kb-cn-stage.netapp.com/on-prem/E-series/SANtricity-OS-Kbs/Host\\_multipath\\_driver\\_configurati...](https://kb-cn-stage.netapp.com/on-prem/E-series/SANtricity-OS-Kbs/Host_multipath_driver_configurati...)

Updated: Wed, 22 Apr 2026 07:30:38 GMT

### 适用场景

E 系列

### 问题描述

- E-Series报告错误事件。

```
Date/Time: 2024-08-23 00:57:43
Sequence number: 165743
Event type: 9103
Event category: Error
Priority: Critical
Event needs attention: true
Event send alert: true
Event visibility: true
Description: Host multipath driver configuration error detected
Event specific codes: 0/0/0
Component type: Host
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Component location: Host <host name>

Logged by: Controller in bay A

- 但是、E-Series上的所有状态均为最佳和正常。