



CXone Mpower EXPERT

如何在 Windows 上排查 E-Series 多路径问题

https://kb-cn-stage.netapp.com/on-prem/E-series/SANtricity-OS-Kbs/How_to_troubleshoot_E-Series_m...

Updated: Wed, 22 Apr 2026 08:24:23 GMT

适用于

- NetApp E 系列
- Windows 主机

描述

本文概述了在 Windows 主机上多路径问题的一般故障排除步骤

多路径问题可能会报告以下一个或多个错误：

- Volume not on preferred path due to AVT/RDAC failover
- Host multipath driver configuration error detected
- Incorrect Host Multipath Driver
- Loss of host-side connection redundancy detected
- ALB_INCOMPATIBLE_HOST_DRIVER-Recovery Failure Type Code: 474

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

