



CXone Mpower EXPERT

E端口分段错误、网络结构ID不匹配

https://kb-cn-stage.netapp.com/on-prem/Switches/Broadcom-KBs/E_port_segmented_error_fabric_ID_...

Updated: Wed, 22 Apr 2026 07:33:11 GMT

适用场景

Brocade交换机

问题描述

在数据中心中移动交换机物理后，ISL端口报告 segmented 错误：

```
Index Port Address Media Speed State Proto
=====
 39 39 0axx00 id 4G Online FC E-Port
segmented,10:00:xx:xx:71:f5:0c:3a (ESC mismatch, Fabric ID)
 47 47 0axx00 id 4G Online FC E-Port 10:00:88:94:xx:xx:0b:7a
"zurinx1swc01-a_55" (downstream) (Trunk master)
```