



CXone Mpower EXPERT

由于镜像速度较慢、存储延迟较长

https://kb-cn-stage.netapp.com/on-prem/Switches/Broadcom-KBs/High_latency_on_Storage_Due_to_s...

Updated: Wed, 22 Apr 2026 07:31:49 GMT

适用场景

ONTAP 9
Brocade
MCC

问题描述

卷镜像速度较慢、导致生产环境速度较慢。