



---

## Brocade SAN 交换机上的FCP延迟较高

[https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/High\\_FCP\\_on\\_Brocade\\_SAN\\_switch](https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/High_FCP_on_Brocade_SAN_switch)

Updated: Wed, 22 Apr 2026 07:30:29 GMT

### 适用场景

- Brocade DCX 交换机
- FCP

### 问题描述

- SAN 主机的 FCP 延迟较高
- Brocade DCX 交换机在 ISL 端口上显示以下消息：
  - `WARNING, DCX_switchname, Severe latency bottleneck detected at slot x port xx.`
  - `INFO, DCX_switchname, Frame timeout detected, tx port -1 rx port x/xx, sid bd800, did 150340, timestamp xxx`

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information