



## CONTAPEXT-收音机：AT托 网桥意外重新启动：警告SWWD

<https://kb-cn-stage.netapp.com/on-prem/ontap/MC/MC-Issues/CONTAPEXT-839>

Updated: Wed, 22 Apr 2026 07:31:33 GMT

### 问题描述

- 对于ATto光纤桥7600网桥 重新启动 `dumpeventlog all` 显示错误：

```
WARN SWWD <####>
INFO SWWD Exception
....
INFO Reset. HW Code: Software Warm
INFO Reset. Reason: Watchdog Timer Interrupt Exception
```

- 对于ATto 7500N网桥重新启动事件日志显示：

```
03C82F 14:32:50 06/10/22 CRIT Data Abort Exception (007A), DFAR= 1f3ec22e, DFSR=
03C830 14:32:50 06/10/22 CRIT 00000001, LR= 00041574
03C831 14:32:50 06/10/22 INFO Data Abort
03C832 14:32:50 06/10/22 INFO 06/10/2022 14:32:50
03C833 14:32:50 06/10/22 INFO ST[006c04a0-006c24a0] | FP[006c23dc] CPSR[60000197]
03C834 14:32:50 06/10/22 INFO 001494b4<-00261ee8 | SP[006c23e0] FP[006c2454]
03C835 14:32:50 06/10/22 INFO 00261e44<-00261540 | SP[006c2458] FP[006c2464]
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

03C836 14:32:50 06/10/22 INFO 0026152c<-0000059c | SP[006c2468] FP[1f3fcffc]  
03C837 14:32:50 06/10/22 INFO FP out of range [6c2464]  
03C838 14:32:50 06/10/22 INFO ST[1f3fc000-1f3fd000] | FP[1f3fcffc] CPSR[60000113]  
03C839 14:32:50 06/10/22 INFO 00041530<-003e6a10 | SP[1f3fd000] FP[1f3fd000]