



CXone Mpower EXPERT

CHW-2739 : AFF A700s : VA 0 上的页面错误 (主管读取指令, 页面不存在) cs:rip 0x20:0 rflags 0x10206 在进程 swi1: mri_ha 中

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CHW-2739>

Updated: Wed, 22 Apr 2026 08:25:16 GMT

问题描述

- AFF A700s 节点出现以下意外重启：
--page fault (supervisor read instruction, page not present) on VA 0 cs:rip 0x20:0 rflags 0x10206 in process swi1: mri_ha on release 9.13.1P10 (C)