



## CONTAP-326891 : 适用于 SSKBE 和 ST\*MM 型驱动器的 NA05/NE05/MS05 FW 版本

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-326891>

Updated: Wed, 22 Apr 2026 10:27:35 GMT

### 问题描述

NA05/NE05/MS05 驱动器固件版本针对 **SSKBE** 和 **STMM** 驱动器包括以下

改进：

- 支持新 NAND
- 一般可靠性改进

下表列出了每个受影响驱动器的部件号和标识：

Part Number	Model ID	Capacity	Update Firmware To
E-X4069A-R6 / E-X4071A-R6	ST1800MM0139	1.8TB	NE05
E-X4123B / E-X4122B / E-X4122A	ST1800MM0129	1.8TB	NE05
E-X4072A-R6 / E-X4070A-R6	ST1800MM0129	1.8TB	NE05
E-X4026B-R6 / E-X4096B-R6	ST600MM0039	600GB	MS05
E-X4025B-R6 / E-X4119B	ST1200MM0009	1.2TB	MS05
E-X4052B-R6	ST1200MM0039	1.2TB	MS05

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

E-X4125B / E-X4126B ST1800MM0149 1.8TB NE05}

Part Number	Model ID	Capacity	Update Firmware To
X341A-R6	X341_SSKBE900A10	900GB	NA05
X342A-R6	X342_SSKBE1T2A10	1.2TB	NA05
X343A-R6	X343_SSKBE1T8A10	1.8TB	NA05
X427A	X427_SSKBE1T8A10	1.8TB	NA05