



## CONTAP-474838 : BMC 固件版本 19.2 的增强功能

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-474838>

Updated: Wed, 22 Apr 2026 07:31:12 GMT

### 问题描述

NetApp AFF A50、AFF A30、AFF A20、AFF C60 和 AFF C30 系统的基板管理控制器 (BMC) 19.2 包括以下错误修复和增强功能，可提高可靠性和安全性：

- CFBMC-6487 IO 卡热插拔支持{-}-
- CFBMC-5925 支持 POST RTS IO 卡
- CFBMC-5437 当不支持的供应商 PSU 连接在两个插槽中时，最好有 EMS
- CFBMC-4617 双因素身份验证，以增强 BMC 登录安全性
- CFBMC-5719 将 BMC 的 OpenSSH 升级到 9.9p1
- CFBMC-5718 将 BMC 的 OpenSSL 升级到 3.0.15
- CFBMC-5832 修复了 OpenSSH 登录失败日志记录中的命令注入漏洞
- CFBMC-5905 当传感器不可读时停止发送"monitor.globalStatus.critical：机箱温度太高.."
- CFBMC-5620 PSU FW 更新增强

"NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information