



---

## CONTACP-55807：控制器重新启动(接管/恢复)后、某些WAFL外部缓存选项被禁用

[https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap\\_OS/FS\\_Issues/CONTAP-55807](https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/FS_Issues/CONTAP-55807)

Updated: Wed, 22 Apr 2026 08:33:51 GMT

### 问题描述

重新启动ONTAP控制器(接管/恢复操作步骤)后、配对节点上的某些外部缓存选项(例如缓存重新恢复和mbuf插入)可能会被禁用。