



CONVA-74054 : 由于vbn处于未初始化状态、反复出现panic

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/FS_Issues/CONTAP-74054

Updated: Wed, 22 Apr 2026 08:49:09 GMT

问题描述

VA 0x18 cs : rip 0x20 : 0xffffffff8f8d2023 rflags 0x10206 in SK processwaf1_expreservedt01 on Release 9.5P15 (C)上的
页面错误(主管读取数据、页面不存在)