



ONTAP升级后、SAN主机丢失LUN的路径

https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/After_ONTAP_upgrade_SAN_hosts_I...

Updated: Wed, 22 Apr 2026 09:00:26 GMT

适用场景

SAN
VMware

问题描述

我们在主机端看到这些警报

```
NMP: vmk_NmpVerifyPathUID:1243: UID of a device (path vmhbal:C0:T11:L83) has changed
from naa.600a098038314c57552b5649526638 (2025-04-13T20:26:29.361Z cpu2:66080) .
2025-04-13T20:19:55.263Z cpu12:24202089)WARNING: NMP: nmp_PspSet:527: Switching to
claimrule PSP "VMW_PSP_RR" for device Unregistered Device.
2025-04-13T20:19:55.263Z cpu12:24202089)WARNING: VMW_SATP_ALUA:
satp_alua_getTargetPortInfo:59: Could not get page 83 INQUIRY length for path
"vmhbal:C0:T13:L80" - Not supported (195887136)
```

所有缺少路径都指向存储上的一个特定适配器。