



ESXi 主机重新扫描操作失败 / 超时

https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/ESXi_host_rescan_operations_fails_...

Updated: Wed, 22 Apr 2026 07:31:20 GMT

适用场景

- ESXi
- ONTAP
- SAN

问题描述

- ESXi HBA 和 / 或存储重新扫描操作失败 / 超时
- `vemkernel.log` 充斥着类似的消息：

```
2022-03-01T08:24:39.699Z cpu2:2097796)WARNING: NMP: nmpCompleteRetryForPath:358:
Retry cmd
```

```
0x5f (0x45d958819b40) to dev "naa.600a098038304559732b4c4576xxxxxx" failed on path "vmhba1:C0:T1:L290"
H:0x1 D:0x0 P:0x0 .
```

```
2022-03-01T08:24:40.698Z cpu2:2097796)WARNING: NMP: nmpCompleteRetryForPath:358: Retry cmd
```

```
0x5f (0x45d958819b40) to dev "naa.600a098038304559732b4c4576xxxxxx" failed on path "vmhba1:C0:T1:L290"
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

H:0x1 D:0x0 P:0x0 .