



未显示新主机WWPN

https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/New_host_WWPN_not_showing_up

Updated: Wed, 22 Apr 2026 07:31:33 GMT

• 适用场景

- SAN
- FCP

问题描述

- 更改WWPN后、主机无法访问LUN
- 中的PRLI故障 `vmkernel.log` :

```
2023-06-05T08:48:17.792Z cpu22:2098494)lpfc: lpfc_cmpl_els_prli:2426: 0:(0):0103
PRLI completes to NPort xb0801 Data: x9 xb2c00 x14 x0
2023-06-05T08:48:17.792Z cpu22:2098494)lpfc: lpfc_els_retry:4855: 0:(0):0108 No
retry ELS command x18001420 to remote NPORT xb0801 Retried:1 Error:x9/x0
2023-06-05T08:48:17.792Z cpu22:2098494)WARNING: lpfc: lpfc_cmpl_els_prli:2446:
0:(0):2754 PRLI failure DID:0B0801 Status:x9/xb2c00
2023-06-05T08:48:17.792Z cpu22:2098494)WARNING: lpfc:
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

lpfc_notify_paths_available:4549: 0:(0):3274 ScsiNotifyPathStateChangeAsyncSAdapter
Num x1 TID x0, DID x0b0801.
2023-06-05T08:51:47.454Z cpu56:2098260)lpfc: lpfc_rportStats:4536: 0:(0) Compression
log for fcp target 0, path is ok, Events: npr=3, devloss=1