



# CXone Mpower EXPERT

---

## 同一端口上出现ONTAP SAN STIO错误

[https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/ONTAP\\_SAN\\_STIO\\_Errors\\_on\\_sam...](https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/ONTAP_SAN_STIO_Errors_on_sam...)

Updated: Wed, 22 Apr 2026 04:07:10 GMT

### 适用场景

- ONTAP
- SAN
- FC

### 问题描述

多个不同的S\_ID发生STIO wqe故障、但全部位于同一端口/适配器上：<PCI number> <port>

示例：

```
cluster::> event log show -event *fcp
```

```
Time                Node                Severity            Event
```

```
-----  
fcp.io.status: STIO Adapter:2c IO WQE failure, Handle 0x2, Type 8, S_ID: 123, VPI:  
3, OX_ID: 3CA, Status 0x3 Ext_Status 0x2
```

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information