



# CXone Mpower EXPERT

---

## 某些FCP路径不可用

[https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/Some\\_of\\_the\\_FCP\\_paths\\_are\\_unav...](https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/Some_of_the_FCP_paths_are_unav...)

Updated: Wed, 22 Apr 2026 04:08:32 GMT

### 适用场景

- ONTAP 9.7
- ESXi 7.0 U3

### 问题描述

- 升级ONTAP后、某些FCP路径不可用。
- 分区配置正确