



A250在ONTAP升级后无法启动

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/A250_fails_to_bootup_after_ONTAP_u...

Updated: Wed, 22 Apr 2026 09:00:29 GMT

适用场景

- ONTAP 9
- AFF A250

问题描述

- ONTAP升级后、A250节点启动失败。

```
Please wait, the system needs additional 6s to complete the update in the background.
```

```
Firmware update complete. System rebooting...
```

```
Firmware update complete. System rebooting...
```

- 重置主板也没有帮助。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information