



节点重新启动后、A400 FC端口关闭

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/A400_FC_port_down_after_node_reboot

Updated: Wed, 22 Apr 2026 08:47:51 GMT

适用场景

- AFF A400
- ONTAP 9

问题描述

- 接管/恢复后、0e和0f端口状态为 LINK DISCONNECTED

```
slot 0: Fibre Channel Target Host Adapter 0e
      (Emulex LPe16000 (XE201) rev. 13, <LINK DISCONNECTED>)
Firmware rev:      12.8.433.0
Host Port Addr:    000000
FC Nodename:       50:0a:09:80:80:f6:8b:e3 (500a098080f68be3)
FC Portname:       50:0a:09:83:80:f6:8b:e3 (500a098380f68be3)
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
Connection:      No link
Switch Port:     Unknown
SFP Vendor Name: AVAGO
SFP Vendor P/N:  AFBR-57F5MZ-NA1
SFP Vendor Rev:  01
SFP Serial No.:  AC2240J02R5
SFP Connector:   LC
SFP Capabilities: 4, 8, 16 Gbit/Sec
slot 0: Fibre Channel Target Host Adapter 0f
      (Emulex LPe16000 (XE201) rev. 13, <LINK NOT CONNECTED>)
Firmware rev:    12.8.433.0
Host Port Addr:  000000
FC Nodename:     50:0a:09:80:80:f6:8b:e3 (500a098080f68be3)
FC Portname:     50:0a:09:84:80:f6:8b:e3 (500a098480f68be3)
Connection:      No link
Switch Port:     Unknown
SFP Vendor Name: AVAGO
SFP Vendor P/N:  AFBR-57F5MZ-NA1
SFP Vendor Rev:  01
SFP Serial No.:  AC2240J036P
SFP Connector:   LC
SFP Capabilities: 4, 8, 16 Gbit/Sec
```

- 执行以下操作后、问题仍然存在
 - 执行LIF和端口down/up
 - FC端口重置
 - 交换电缆
 - 更换交换机和存储端口SFP