



CXone Mpower EXPERT

自动注销：BMC 系统控制台因不活动而断开连接

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Autologout%3A_BMC_System_Consol...

Updated: Wed, 22 Apr 2026 11:57:58 GMT

适用于

- BMC 18.3P2 及以下：
 - FAS70 和 FAS90
 - AFF A70、A90、A1K 和 C80
- BMC 19.1P1 及更低版本，用于
 - FAS50
 - AFF A20、A30、A50、C30 和 C60

问题描述

- BMC 控制台连接在 1 分钟后超时：

`Autologout: System Console being disconnected due to inactivity`

- 修改了 ONTAP CLI 中的超时，问题仍然存在：

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
cluster::> system timeout show
CLI session timeout: 480 minutes
```