



AutoSupport 发出 SP HBT 未命中警报

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Autosupport_raises_SP_HBT_MISSE...

Updated: Wed, 22 Apr 2026 07:12:33 GMT

适用场景

- FAS2552
- FAS2554
- FAS2620

问题描述

AutoSupport 会在不重新启动系统且不影响业务的情况下发出以下警报。

示例：

```
HA Group Notification from hostname (SP HBT MISSED) NOTICE
```

同时，SP 日志会显示以下错误消息。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

示例：

```
Thu Jan 1 00:00:41 1970 [IPMI.notice]: 8a01 | c0 | OEM: ffff70005200 |  
ManufId: 150300 | SP Reset Due to Panic
```