



## Bat 3.0伏严重不足

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Bat\\_3.0V\\_is\\_critical\\_low](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Bat_3.0V_is_critical_low)

Updated: Wed, 22 Apr 2026 10:17:10 GMT

### 适用场景

- FAS2554
- FAS2520
- ONTAP 9

### 问题描述

- EMS报告 Bat 3.0V is critical low。

```
[?] Tue Aug 02 00:47:36 CST [Node A: env_mgr:  
monitor.chassisPower.degraded:warning]: Chassis power is degraded: Bat 3.0V is  
critical low (1387 mV). Please replace the CMOS coin cell battery.
```

- SP-LATEST-IPMI 报告 Bat\_3.0V 失败。

```
| Bat_1.5V | 1.504 | Volts | ok | 1.280 | 1.348 | 1.649 | 1.727 Bat_3.0V | 1.
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

430 | Volts | cr | 2.545 | 2.703 | 3.504 | 3.575 Bat\_8.0V | 7.900 | Volts |  
ok | 6.000 | 6.600 | 8.600 | 8.700 Bat\_Curr | 0.000 | Amps | ok | na | na |  
0.800 | 0.900 Bat\_Capacity | 2.304 | Amps\*hour | ok | na | na | na | na Bat\_  
Run\_Time | 148.000 | hour | ok | 76.000 | 78.000 | na | na Bat\_Temp | 27.  
000 | degrees C | ok | 0.000 | 10.000 | 55.000 | 64.000