



BMC 更新失败，并出现错误 221

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/BMC_update_fails_with_error_221

Updated: Wed, 22 Apr 2026 04:09:18 GMT

适用场景

- AFF A250
- FAS500f
- BMC 更新

问题描述

- 从 ONTAP 更新 BMC 失败
- 我们在 SP-MGMT-MLOG-TXT.GZ 中看到以下内容

```
ERR: Servprocd::SpUpdate: bmc_update_cpmi_t: cpmi_get_fw_update_info() returned error code (221). Terminate the update session
```

要查看此错误是否可能影响 **BMC** 固件更新，请运行以下命令：

```
:::>vserver services web show -name FW_BMC -fields ssl-only vserver name ssl-only
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

C1_sti105-vsimsim-ucs558o_1622669176 FW_BMC true