



X1148A卡上的两个端口均已关闭

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Both_ports_down_on_X1148A_card

Updated: Wed, 22 Apr 2026 04:09:20 GMT

适用场景

- AF-A400
- X1148A

问题描述

- 已插入QSFP,但未显示QSFP
- 适配器上的两个端口均显示为关闭：

slot 5: Dual 40G/100G Ethernet Controller CX5 e5a MAC Address: xx:xx:xx:xx:xx:xx(auto-unknown-fd-down)
e5b MAC Address: yy:yy:yy:yy:yy:yy(auto-unknown-fd-down)