



CXone Mpower EXPERT

控制器上的链路e1a已关闭导致ClusterSwitchConnectionDeded_Alert

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/ClusterSwitchConnectionDegraded_Al...

Updated: Wed, 22 Apr 2026 08:24:23 GMT

适用场景

- AFF-A70
- 部件 X50130A：双40G/100G以太网控制器CX6-DX
- 采用NX-OS 10.3 (6)的集群交换机Cisco Nexus NX9336C)
- RCF 1.11

问题描述

- 控制器上的链路e1a已关闭导致系统触发警报ClusterSwitchConnectionDeded_Alert
- 交换机端口已通过缆线SNT SFP 交换确认工作正常
- 更换SFP不能解决问题描述问题、端口仍为链路关闭。
- 节点上的端口发生故障不会解决问题描述问题
- 关闭并重新打开节点电源不会解决问题描述问题

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information