



更换发生故障的磁盘后，磁盘仍呈琥珀色指示灯

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Disk_remains_amber_light_after_repla...

Updated: Wed, 22 Apr 2026 08:49:16 GMT

适用场景

- ONTAP 9
- Data ONTAP 8
- I/O 模块 (IOM)

问题描述

更换发生故障的磁盘后，磁盘仍呈琥珀色指示灯。