



---

## EMS 日志引发 "SPLinkDownAlert"

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/EMS\\_log\\_raises\\_SPLinkDownAlert](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/EMS_log_raises_SPLinkDownAlert)

Updated: Wed, 22 Apr 2026 08:36:02 GMT

### 适用场景

- FAS2552
- FAS2554
- FAS2720
- AFF8040
- AFF A300
- ONTAP 9

### 问题描述

EMS日志会引发以下 "SPLinkDownAlert" 错误、然后会在几分钟内自动清除。

```
</LR>
```

```
<LR d="03Jul2020 08:55:28" n="hostname" t="1593734128" id="0/17489106829313"  
p="1" s="Ok" o="nphmd" vf="" type="1" seq="159721">
```

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
<hm_alert_raised_1
detailed_info="Alert Id = SPLinkDownAlert , Alerting Resource = SP Config"
monitor="controller"
alert_id="SPLinkDownAlert"
alerting_resource="SP Config"/>
</LR>
</LR>
<LR d="03Jul2020 09:05:28" n="hostname" t="1593734728" id="0/17489106829314"
p="6" s="Ok" o="nphmd" vf="" type="1" seq="159723">
<hm_alert_cleared_1
detailed_info="Alert Id = SPLinkDownAlert , Alerting Resource = SP Config"
monitor="controller"
alert_id="SPLinkDownAlert"
alerting_resource="SP Config"/>
```